Weathertzetton Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0864/1

Work Order Type: Weatherization

Audit Name: 17017UC-0864

CLIENT INFORMATION

Client ID: 17017UC-0864

AGENCY INFORMATION

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 *Email Address:*

Agency Contact: Carlisle, Ron Work Phone:

Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature	

COMMENT

1961 site built home with 1701 sq. ft

Measures

1	Measure 1	Auto 9 VE	matic Foundation Vent	s 8" x 16	" X	Componen	its			Inspected
C	omment									
						Estimated	<u> </u>		Actual	
#	Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Construction Materials/Ha e		Install Foundation Vents	Each	9					
C	ther Detail									
					Measur	e Sub Total:		,	Sub Total:	
	SE	JCTS: :AL/ R :AL/ R	EPAIR DUCT REGISTE EPAIR DUCTS W/ MAS' SIDE RETURN AIR VEN	TIC X 12			ALL CAV	TTY)	Actual	Inspected
#	Material / Lat	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Miscellaneou Supplies		Duct Sealing	Each	1		rotur			Total
C	ther Detail									1
					Measur	e Sub Total:] ,	Sub Total:	
	Field Notes:									

Inspected **Measure 3** Infiltration Redctn **Components** Comment ATTIC ACCESS DOOR W/R-30 & WEATHERSTRIPPING X 2 **INSTALL 2 DOOR SWEEPS CAULK AND GLAZE 13 WINDOWS Estimated** Actual # Material / Labor **Unit Cost Unit Cost Description / Comment** Units Qty Total Qty Total 10 Miscellaneous Infiltration Reduction Each 1 Supplies Other Detail Measure Sub Total: Sub Total: Field Notes: Inspected **Measure 4** DWH Pipe Insulation **Components** Comment **Estimated** Actual # Material / Labor **Description / Comment Units Unit Cost** Total **Unit Cost** Total Qty Qty 1 Insulation **DHW Pipe Insulation** Each 1 wrap water pipes 2 Labor **DHW Pipe Insulation** Each Other Detail Sub Total: Measure Sub Total: Field Notes:

Measure 5 Attic Ins. R-38				Components ATC				
Comment AUDIT	OR CALLS FOR R-30							
			Estimated	1	Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1638					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Measure 6 DV	VH Tank Insulation			Componen	its		ı	Inspected
Measure 6 DV Comment	VH Tank Insulation			-				Inspected
Comment		Units		Estimated	<u> </u>	Otv	Actual	
Comment # Material / Labor	WH Tank Insulation Description / Comment DHW Tank Insulation	<i>Units</i> Each	Qty 1	-		Qty		Inspected Total
Comment# Material / Labor1 Hot Water	Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Hot Water Equipment	Description / Comment DHW Tank Insulation R-10 minimum-use		Qty	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Hot Water Equipment	Description / Comment DHW Tank Insulation R-10 minimum-use bubble wrap	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Hot Water Equipment 2 Labor	Description / Comment DHW Tank Insulation R-10 minimum-use bubble wrap	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Hot Water Equipment 2 Labor	Description / Comment DHW Tank Insulation R-10 minimum-use bubble wrap	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Hot Water Equipment 2 Labor	Description / Comment DHW Tank Insulation R-10 minimum-use bubble wrap	Each	Qty 1	Estimated	<u> </u>		Actual	

Measure 7 Flo Comment	or Ins. R-19			Componen				Inspected
# ##= (= vi=1 / 1 = b = v	D = 1.45 = 1.00 = 1.00	11-11-		Estimated	 -		Actual	T-1-1
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation <i>-</i> Fiberglass Batts - R-19	SqFt	1638					
Other Detail			1			1		
]		
			Measur	e Sub Total:			Sub Total:	
Measure 8 Sto Comment A: 36X C: 51X	46 {3}			Componen	ts C3,A1		,	Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
3 Other	Storm Window	Each Window	4					
	<99 U.I ea Over 100 UI							
Other Detail								
] []					
			Magazir	e Sub Total:]	Sub Total:	
			weasur	e Sub Total:		'	oub rotar.	
Field Notes:								

Report Run On: 5/21/2010

-		Moisture Problems sement/Crawlspace) 163	8 SQ. FT		Componen	ts			Inspected
C	Comment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Moisture Barrier Needed	SqFt	1638					
2	Labor	Labor	Hour	1					
C	Other Detail								
Ī									
				•	0.1.7.4.1]	Sub Total:	
				Measur	e Sub Total:			Sub Total:	
	Measure 10 Insta	all Bathroom Exhaust Fa	an		Componen	ts			Inspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Bathroom exhaust fan w/light & damper	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:			Measure	e Sub Total:		,	Sub Total:	

ı	Measure 11 Install Kitchen Exhaust Fan				Componen	ts	Inspected			
C	Comment									
					Estimated	<u> </u>		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	Kitchen exhaust fan w/ damper	Each	1						
2	Labor	Labor	Hour	1						
C	Other Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									
Ĺ										
			Work Or	der Gra	and Total:		Gran	d Total:		